

Technical Bulletin

Model
911C2/C4/t

Group
6

Subject:
Ashtray Covers

Part Identifier
6820

Number
9102

ATTENTION: Service Manager/Service Technician

Models Affected: 911 Carrera 2/4, 1991— 911 turbo

Concern: Should replacement of the ashtray assembly become necessary, the outer trim cover must be transferred from the old part to the new part.




Figure 1

Service Information: To remove cover, carefully pry the locking tabs up and slide the cover to disengage the locking hooks (Figure 1).

Warranty Claim Information:
Labor Operation: 6820190A
Damage Code: 6820100002
Time Units: 20

Parts Information:
Ashtray Assembly 964 552 923 00
Ashtray Insert 964 552 925 00

PORSCHÉ CARS NORTH AMERICA, INC.

