

Technical Bulletin

Model
911 C2/C4/T
944, 968

Group
1

Subject:

Cooling Fan Motor

Part Identifier
1756

Number
9305


ATTENTION: Service Manager / Service Technician

Models Affected:

924 S All
944 1983–
944 S All
944 S2 All
944 Turbo All
968 All
911 Carrera 2/4 1989–
911 Turbo 1991–

Concern:

Correct positioning of the cooling fan motor for the A/C condenser and oil cooler on 6 cylinder models and radiator cooling fan on 4 cylinder cars.



5mm Vent

Installing:

When replacing or installing the cooling fan motor in any of the above mentioned vehicles, if the motor casing has a vent hole, it must point downward.

Always be sure that the correct part number for the intended application is used.

Parts Information:

Description

Part Number

Radiator cooling fan motor

944 624 021 03

A/C condenser fan motor

964 624 035 01

Oil cooler fan motor

964 624 035 00

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

