

# Technical Bulletin

Model  
911 C2

Group  
4

**Subject:** Front Wheel Carrier Cover

**Part Identifier**  
4050

**Number**  
9207

**ATTENTION: Service Manager/Service Technician**

**Models Affected:** *911 Carrera 2 from Model Year 1990*

**Concern:** Loose or missing cover(s) on the inside of the front wheel carrier(s).

**General Information:** As of production date August 10, 1992, new covers for the inside of the front wheel carrier have been installed. The new covers have been modified with stronger mounting tabs.

**Vehicle Information:** The new covers are installed from the following VIN's:

Coupe - WP0 AB2 965 PS 42 0109  
Targa - WP0 BB2 961 PS 44 0071  
Cabriolet - WP0 CB2 966 PS 46 0112

**Parts Information:** The part number for the new cover is 964 341 252 02. When repairing vehicles for loose or missing covers, only the above part should be used.

**Warranty Information:** Damage Code: 4064 1000 02

Labor Operation: 4064 4900

Time Units: 20

